



BG-Series

	BG60	BG61	TC8.1	
•	•	•	•	 Workpiece Measurement
		•	•	 Temperature Measurement
•	•	•	•	 Radio Transmission
•	•			 Wear-free Measuring Mechanism
•	•	•		 Mass Production
•	•			 Diameter Measurement
		•		 Position Measurement
		•		 Roundness Measurement
		•		 Cylindricity Measurement
		•		 Concentricity Measurement

